

Figure 1





Figure 2

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
CRAFTSMAN		




Figure 3

APPROVED	O.G. FIG. 4	
BY	CLASS	SUBCLASS
DRAFTSMAN	710	62




Figure 4

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 5

APPROVED	C.G. FIG.	
BY	CLASS	SUBCLASS
CRAFTSMAN		

	601	602	603
	COMMAND	COUNT	ADDRESS
0001:	START TAPE		
0002:	SYNCH		
0003:	WAM		
0004:	WRITE DATA		
0005:			
0006:			
0007:			
0008:			
0009:			
.			
.			
9999:			

Figure 6

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 7(a)

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
CRAFTSMAN		




Figure 7(b)

APPROVED	C.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 8

APPROVED	O.C. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 9

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 10

APPROVED	C.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 11




Figure 12

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 13

MS-DOS ADDRESS SPACE




Figure 14




Figure 15
(Prior Art)




Figure 16